e 5.5e [Date 8-2-15 Linthicam W.O Number 2025270, Watchman spected From Landen Exception Chain Marker No. W.C. Track Rall Switch Status Repair Item From Number To No. E/W No. Comp. Defect S/Y/R Y/N 1. der bereit with the 2. 3. 4. 5. 6. 7. 8. 9. Item **COMMENTS** New Defects Noted Area. Lander 9:00 AM 930 westport 10'00 4m N. Linthicum 1070 North AVENUE Were Switch in the area of Inspected Yes __ NO Were all single operating mechanism & conecting rod type switches inside area and operatated in each position? __NO__ Yes_ SPECIAL INSPECTION Yes____ NO____ Reason for special Inspection ? _____ Supervisory Cretification